UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,178,679 B2

Page 1 of 1

APPLICATION NO.: 10/767389

DATED

: February 20, 2007

INVENTOR(S)

: Mark E. Canty et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8, Line 33 should read: -- and away from the base die. In particular, due to the geometry--

Column 8, Line 54 should read: --formed between the lower center and lower left dies--

Signed and Sealed this

Sixteenth Day of October, 2007

JON W. DUDAS Director of the United States Patent and Trademark Office